Assignment of connection line

Connection colours for temperature sensors with connection line

Version with single and multiple elements

This figure indicates the number of measuring resistors and is entered in front of the element.The additional letter belonging to the circuit is added to the element.Example : <u>2 Pi</u> stands for <u>2x Pt100 with 1x 3 - and 1x 4-wire technique</u>

2 – wire technique is the standard (without additional letter)

